



Hi-Tec Oil Traders Pty Ltd ABN 28 053 837 362

5 Tarlington Place Smithfield NSW 2164

Correspondence: P.O Box 322 Castle Hill NSW 1765

Ph: 1300 796 009 | Fax: (02) 9604 1611 | Email: hitecoils@hi-tecoils.com.au

www.hi-tecoils.com.au

PRODUCT DATA SHEET

POWER STEERING STOP LEAK

PRODUCT DESCRIPTION

Power Steering Stop Leak is designed to help prevent leaks in the power steering system by revitalizing the rubber seals and O-rings. It quiets and smooths power steering operations and restores performance. The product contains seal swell and special additives that not only lubricate and smooth hardened or shrunken seals to prevent further leaks but also impart excellent anti-wear and anti-corrosion protection to the affected parts. **Power Steering Stop Leak** can reduce slack, squeals, and hard spots in worn rack & pinion systems.

Power Steering Stop Leak is suitable for most power steering systems and is an ideal for passenger cars, 4WD and light commercial vehicles.

DIRECTIONS FOR USE

Before using the product check the condition of the existing fluid. If dirty, it should be changed, as dirt and sludge are major threats to smooth operation. In addition, replacing old contaminated fluid can extend the life of the entire power steering system.

Remove the power steering dipstick and check reservoir fluid level. Add one 300 mL bottle of **Power Steering Stop Leak** into reservoir and top up as necessary or as per manufacturers specifications. Drive for about 5 to 10 minutes to circulate the fluid. Check fluid level again and top up if necessary. It may be necessary to drain some fluid out of power steering reservoir to enable the full contents of this bottle to be added.

Do not overfill. In seriously damaged power steering systems, it is suggested that the power steering fluid be changed or replaced.

It is recommended that the treatment be repeated every 12 to 18 months (depending on the vehicle) to prevent leaks from occurring unexpectedly and ensure ongoing performance. Under normal circumstances 300 mL of **Power Steering Stop Leak** is sufficient to treat most power steering units but some older systems may require several treatments before efficiency and benefits are noticed.

Depending on the power steering problem, the potential of the **Power Steering Stop Leak** may be noticed immediately or it may take a few days of driving.

If leaks persist after treatment, the seals may be severely damaged in which case they should be replaced.



AUSTRALIAN FAMILY OWNED SINCE 1989





Hi-Tec Oil Traders Pty Ltd ABN 28 053 837 362

5 Tarlington Place Smithfield NSW 2164

Correspondence: P.O Box 322 Castle Hill NSW 1765

Ph: 1300 796 009 | **Fax:** (02) 9604 1611 | **Email:** hitecoils@hi-tecoils.com.au

www.hi-tecoils.com.au

PRODUCT DATA SHEET

Available in: 300 mL

"Hi-Tec Oil Traders Pty Ltd (Hi-Tec Oils) has endeavoured to ensure that all information, representations and specifications contained in this product data sheet are accurate at the time of publication. This general information should be used in conjunction with appropriate inquiries by users of the product including consultation with the vehicle or equipment manufacturers published information.

It is the responsibility of users of the product to use the product safely. Users should consult the safety data sheets for each product at www.hi-tecoils.com.au. Hi-Tec Oils takes no responsibility for injury or damage if the product is used in an inappropriate or unsafe manner.

Our product warranty and product quality statement can be viewed at www.hi-tecoils.com.au"

Item code: HI14-PSSL-300

Effective: March 2020

MR023040/1



AUSTRALIAN FAMILY OWNED SINCE 1989

